Correction of the AC Component of the Color **Registration Error in a Tandem-Type Color Laser Printer**

Mun-Bo Shim

Technology Strategy Office, Corporate Technology Operations, Samsung Electronics Co. Ltd., Digital Research Center 31F, 416 Meatan-3 dong, Yeongtong-gu, Suwon City, Kyunggi-do 443-742, Korea E-mail: munbo.shim@samsung.com

Soo-Yong Kim

Digital Printing Division, Digital Media Business, Samsung Electronics Co., Ltd., Digital Research Center 33F, 416 Meatan-3 dong, Yeongtong-gu, Suwon City, Kyunggi-do 443-742, Korea

Abstract. A new method is proposed for correcting the ac component of the color registration error in the paper feeding direction in a tandem-type color laser printer. The main factor of the ac color registration error is the fluctuation of the angular velocity of organic photoconductive drums caused by gears with runout in multiple gear systems. In order to express the fluctuation mathematically, the kinematical relation between a pair of gears with runout is constructed and it is extended into a multiple gear system. Also, the specific reduction ratio in the multiple gear system is proposed as a necessary condition for the correction of the ac color registration error. With the ac color registration error obtained by integrating the angular velocity, the optimization problem is formulated in terms of the installation phase of the gears with runout. A continuous evolutionary algorithm is used to find the optimal installation phases. © 2008 Society for Imaging Science and Technology.

[DOI: 10.2352/J.ImagingSci.Technol.(2008)52:5(050502)]

INTRODUCTION

The market demand for high-speed performance of a color laser beam printer led to development of tandem-type color printers, which have four organic photoconductive (OPC) drums to develop four colors (cyan, magenta, yellow, and black). Although the conventional system with one drum uses a four cycle process to create a full color image, the tandem system can produce the image with just one cycle. Therefore, the tandem system can achieve high speed. However, it introduces a problem of color registration, which did not occur in the single drum system.

The achievement of high image quality as well as of high-speed performance is the key of success of a color printing system. Image quality is typically rated as the number one reason for selecting the product.¹ Color registration, among several problems that may occur in a color laser printer, has conceivably the most harmful influence on image quality. It can affect other image quality attributes including text and line quality, color uniformity. Therefore, it is important to achieve accuracy of color registration for high image quality in all color laser printers.

1062-3701/2008/52(5)/050502/9/\$20.00.

Color registration error is generally defined as the difference of position among the four color lines/dots on the printed images. It occurs along both the laser scanning direction and paper feeding direction. It also consists of the fluctuation of the registration error (the ac component) and the average error (the dc component). It is well known that the registration error along the laser scanning direction can be corrected electrically and the correction of the dc component of the registration error is mainly performed by the electrical and optical system of the laser scan unit (LSU).^{2,3} It has been found that the ac component is mainly introduced by the fluctuation of the angular velocity of OPC drums, although it may involve various causes.⁴ However, the correction of the ac component as well as the relation between the color registration error and the velocity fluctuation has never been described from the mechanical point of view.

In this article, the ac component of the color registration error in the paper feeding direction is corrected through the adjustment of the installation phases of gears with runout. The fluctuation of the angular velocity of OPC drums is mainly caused by gears with runout in the driving unit. In order to express the fluctuation mathematically, the kinematical relation between a pair of gears with runout is constructed and it is extended into a multiple gear system. Also, the specific reduction ratio in a multiple gear system is proposed as a necessary condition for the correction of the ac color registration error. With the ac color registration error obtained by integrating the angular velocity of each drum, the optimization problem is formulated in terms of the installation phase of the gears with runout. A continuous evolutionary algorithm (CEA), which was introduced in previous studies^{5,6} is used to find the optimal installation phases of the gears.

AC COMPONENT OF COLOR REGISTRATION ERROR

The position variation ΔY , which is defined as the difference between the regular (or ideal) position and the printed one on the image, becomes the ac component of the color registration along the paper feeding direction as shown in Fig-

Received Feb. 15, 2008; accepted for publication Jul. 2, 2008; published online Sep. 19, 2008.



Figure 1. ac component of color registration error expressed by the position variation.

ure 1. It is mainly introduced by the fluctuation of the angular velocity of OPC drums. The fluctuation is in turn related to a multiple gear system including gears with runout. For cost reasons, the drums are generally driven by one motor through the gear system. If the four OPC drums are each driven by gears with runout, each drum will have different fluctuations in its surface velocity. Owing to the fluctuations, the images on the OPC drums are not developed regularly in space even under the constant scanning interval of laser units. After transferring to paper occurs, the image affected by the velocity fluctuations is shown in Fig. 1.

The correction of the ac component as well as the relation between the color registration error and the fluctuation caused by gears with runout has never been described from the mechanical point of view. Similarly to the correction of a dc component,^{2,3} it may be performed through the optical system based on feedback control. However, the system will require some additional sensors/processors and the product cost will increase. Owing to the structure driven by one motor through the gear system, it is not certain whether such correction is easy to achieve or not.

PROBLEM STATEMENT

Figure 2 is a schematic diagram of the tandem color laser printer to which the proposed method is applied. The printer, which transfers the colors one by one onto the paper directly, is equipped with LSUs, four-color developing units with four OPC drums, a paper transfer belt with transfer rollers, and a fuser unit. As four OPC drums are driven by one motor and the gears in the driving system have runout, the angular velocity of each drum is fluctuated without any treatment, such as an additional control system or use of



Figure 2. Schematic diagram of tandem color laser printer.

precise gears, which does not prove meaningful from the economic point of view.

The fluctuation which generates the ac component of the color registration error between exposure to transferring in electrophotographic printing is shown in Figure 3. Assuming that the exposure by the LSU is done in time and there is no slip transferring, the position (Y) of a dot on the image can be obtained by integrating the linear velocity of a drum at a transfer point. The difference of the positions generated by the four colors becomes the color registration error.

The purpose of this study is to correct the ac component of the color registration error in the paper feeding direction through the adjustment of the installation phases of



Figure 3. Diagram of exposure to transferring in the EP process.

gears with runout. The ac component is caused by the position variation of the four colors. The problem of this correction can be stated as follows

Minimize:

$$f(e_i, \varphi_i) = \max(\Delta Y_{\text{yellow}}, \Delta Y_{\text{magenta}}, \Delta Y_{\text{cyan}}, \Delta Y_{\text{black}}) - \min(\Delta Y_{\text{yellow}}, \Delta Y_{\text{magenta}}, \Delta Y_{\text{cyan}}, \Delta Y_{\text{black}})$$
(1)

where *e* is gear's runout or eccentricity, φ is the installation phase of the gear, and *i* is the number of gears of interest. According to Eq. (1), the correction of the ac component means the synchronization of the position variation of four colors on the image. The range of the installation phase is within 2π . A continuous evolutionary algorithm is used to find the optimal installation phases of the gears.

In advance of obtaining the optimal installation phases, the specific reduction ratio of the gears must be determined in a multiple gear system. If the angular velocity of each drum changes with a different period, it is sometimes impossible to synchronize the position variation of the four colors. Therefore, the proper reduction ratio, i.e., the number of teeth on the gears, is determined before correcting the color registration error.

CORRECTION OF COLOR REGISTRATION ERROR

The correction of ac component of the color registration error in the paper feeding direction requires finding the installation phases of gears with runout that minimize the position variation generated by four colors OPC drums connected with a multiple gear system. This section presents technical details of the proposed method: (1) reduction ratio for synchronization, (2) kinematical relation between a pair of gears with runout, and (3) continuous evolutionary algorithm.

Reduction Ratio for Synchronization

Synchronization is an important design consideration in tandem-type color printers. In order to synchronize the position variation of four colors on the image, the time when the paper travels from one color transfer point to the next, what we call OPC pitch should be an integral number of the rotational period of each OPC drum. This is a necessary condition for the synchronization of the position variation.

Figure 4 is a schematic diagram of a multiple gear sys-



Figure 4. Schematic diagram of multiple gear system.

tem, which is included in the tandem color laser printer. Let L be the OPC pitch and d_{drum} be the diameter of a drum. Assuming that the paper slip may be neglected, the process velocity of the paper can generally be expressed as

$$V_{\rm paper} = V_{\rm opc} = \frac{d_{\rm drum}\omega_{\rm opc}}{2}$$
(2)

where ω_{opc} is the angular velocity of a drum and V_{opc} is the linear velocity of the drum at a transfer point. To synchronize the position variation of four colors on the images,

$$\frac{\Delta t}{T} = \frac{L/V_{\text{opc}}}{2\pi/\omega_{\text{opc}}R_i} \cong k \tag{3}$$

must be satisfied, where Δt is the time in which the paper travels the OPC pitch, and *T* is the period of the drum. R_j is the reduction ratio from *j*th gear in the multiple gear system to a OPC coupling one and *k* is an integer. Eq. (3) can be rewritten as

$$\frac{L}{\pi d_{\rm drum}} \frac{1}{R_j} \cong k \tag{4}$$

Generally, the reduction ratio in the gear system is determined, depending on the design specification. However, if the number of teeth of the gears each in the multiple gear system is modified based on Eq. (4) without any change, or with a small change of the entire reduction ratio, a necessary condition for the synchronization of the position variation can be reached.

Kinematical Relation Between a Pair of Gears with Runout

The color registration error caused by a gear system is the vibration in a low frequency band. The gear dynamics literature includes a large number of dynamics models, which are aimed at predicting dynamic characteristics of gear



Figure 5. Geometrical configuration of the mesh of a perfect pinion and a gear with runout.

systems.^{7–9} However, there are a few studies on the transmission deviation caused by gears with runout in a low frequency band.^{10,11} Further, they regard the runout as an eccentricity without considering the actual runout profile. In this article, the kinematical relation between a pair of gears with runout, namely, the fluctuation of the angular velocity, is established based on the position deviation on the line of action. As it is obtained by assuming that the runout of the gear is sinusoidal, it is easily updated with the actual runout profile via the Fourier series. The transmission deviation is obtained by integrating the fluctuation of the angular velocity and the color registration error is expressed in terms of the installation phase of the gears with runout.

To calculate the fluctuation of the angular velocity of OPC drums in the multiple gear system, a mathematical expression between a pair of gears with runout is derived. In Figure 5, there are the driving and driven gears, respectively. For simplicity, only one has runout and the other is perfect. Let O_1 , O_2 be the centers of rotation of the gears and r_{b1} , r_{b2} be their base radii. Assuming that the runout of the driven gear is sinusoidal as shown in Figure 6, the base radius instantaneously ranges from $r_{b2}-e_2$ to $r_{b2}+e_2$, where e_2 is the amplitude of the runout in a rolling chart, i.e., eccentricity. The change of the base radius of the driven gear causes the variation of the pitch point whose peak-to-peak amplitude is $2\varepsilon_2$. Therefore, the fluctuation of the angular velocity of the driven gear at constant angular velocity of the driving gear can be obtained as

$$\omega_2(t) = \frac{r_{p1} - \varepsilon_2 \sin(\omega_1 t/R + \varphi_2)}{r_{p2} + \varepsilon_2 \sin(\omega_1 t/R + \varphi_2)} \omega_1$$
(5)

where r_{p1} , r_{p2} are the radii or the pitch circles; *R* is the reduction ratio; and φ_2 is the installation phase relative to a datum point where the runout is measured.

The variation of the pitch point expressed in term of the runout is derived from the observation of the movement of the line of action as depicted in Figure 7. Let *F* be the pitch point when there is no runout in a gear system and *E*, *G* be the intersecting points of the center distance $(\overline{O_1O_2})$ and the lines of action. The variation of the pitch point is equal to



Figure 6. Rolling chart and X-Y plot of runout.



Figure 7. Variation of the pitch point by a gear with runout.

the summation of the lines *EF* and *FG*. First, the Law of Sines is applied to the triangle $\Delta O_1 AF$ in order to obtain \overline{EF} within the variation of the pitch point.

$$\frac{r_{p1} - EF}{\sin(\pi/2 - \alpha)} = \frac{r_{b1}}{\sin(\pi/2 - \alpha - \phi)},\tag{6}$$

where α is the angle $\angle BAC$ generated by the movement of the line of action and ϕ is the pressure angle. Although the line of action through the pitch point *E* does not pass point *A* exactly, the discordance is so small that we can neglect it. Eq. (6) implies

$$\overline{EF} = r_{p1} - \frac{r_{b1}}{\cos\phi + \sin\phi\tan\alpha},\tag{7}$$

where

$$\cos \phi = \frac{r_{b1} + r_{b2}}{l}, \quad \sin \phi = \frac{\sqrt{l^2 - (r_{b1}^2 + r_{b2}^2)^2}}{l},$$
$$\tan \alpha = \frac{e_2}{\sqrt{l^2 - (r_{b1}^2 + r_{b2}^2)^2}}.$$
(8)

Substituting Eq. (8) into Eq. (7), we obtain the line EF as

$$\overline{EF} = r_{p1} - \frac{lr_{b1}}{r_{b1} + r_{b2} + e_2}.$$
(9)

The remaining of the variation of the pitch point \overline{FG} is determined in the same manner:

$$\overline{FG} = -r_{p1} + \frac{lr_{b1}}{r_{b1} + r_{b2} - e_2}.$$
 (10)

Finally, the variation of the pitch point expressed in term of the runout is

$$\varepsilon_2 = \frac{le_2 r_{b1}}{(r_{b1} + r_{b2})^2 - e_2^2}.$$
 (11)

According to the previous procedure, the fluctuation of the angular velocity of the driven gear in a pair of gears with runout can be obtained by linear superposition of the variation of the pitch point expressed in term of the runout:

$$\omega_2(t) = \frac{r_{p1} + \varepsilon_1 \sin(\omega_1 t + \varphi_1) - \varepsilon_2 \sin(\omega_1 t/R + \varphi_2)}{r_{p2} - \varepsilon_1 \sin(\omega_1 t + \varphi_1) + \varepsilon_2 \sin(\omega_1 t/R + \varphi_2)} \omega_1.$$
(12)

In addition, it is extended into a multiple gear system to express the fluctuation of the angular velocity of OPC drums. At that time, a gear drives an adjacent one with phase lag/lead of the runout simultaneously when it is driven.

The positions of dots on the image can be obtained by integrating the linear velocity of an OPC drum, respectively. The change of an OPC drum in the radial direction is ignorable as the diameter of a drum is far greater than the change of the radius of the coupling gear. In addition, the angular velocity caused by the actual runout profile can be obtained by modifying Eq. (5) after the profile is represented approximately by the Fourier series.

Continuous Evolutionary Algorithms

Evolutionary algorithms (EAs) are probabilistic optimization algorithms based on the model of natural evolution; such algorithms have clearly demonstrated their capability to create good approximate solutions in complex optimization problems.

CEAs^{5,6} are one set of EAs, which is specifically formulated for the optimization with continuous search space. The reproductive operations of CEAs are intended to be similar to those of genetic algorithms (GAs) such that it can take the advantage of probabilistic features in GAs. The major difference of CEAs from GAs is that a search point itself, i.e., a real continuous vector, gives the representation of the individual. First, a population of individuals, each represented by a continuous vector, is initially (generation n=0) generated at random, i.e.,



Figure 8. Multiple gear system driving OPC drums.

$$P^n = \{x_1^n, \dots, x_\lambda^n\},\tag{13}$$

where x represents the vector of real variables and λ is the number of parental individuals in the problem.

The definition of the recombination and mutation becomes the probabilistic distribution of the phenomenological measures accordingly. The recombination operation is then defined as

$$x_a^{n+1} = (1 - \mu_a^n) x_a^n + \mu_b^n x_b^n,$$

$$x_b^{n+1} = \mu_a^n x_a^n + (1 - \mu_b^n) x_b^n,$$
 (14)

where x_a^n , x_b^n are parental individuals at generation *n* and parameter μ_i^n , $\forall i \in \{a, b\}$ may be defined by the normal distribution with mean 0 and standard deviation σ

$$\mu_i^n = \text{gauss}(0, \sigma^2). \tag{15}$$

The mutation can also be achieved simply by implementing

$$x^{n+1} = \operatorname{rand}(x_{\min}, x_{\max}).$$
(16)

The evaluation of the fitness can be conducted with a linear scaling, where the fitness of each individual is calculated as the worst individual of the population subtracted from its objective function value

$$\Phi(x_i^n) = \max\{f(x^n) | x^n \in P^n\} - f(x^n), \quad \forall \ i \in \{1, \dots, \lambda\}.$$
(17)

Proportional selection, which is the most popular selection operation in GAs, is also directly used in CEAs. Optionally, ranking selection can be implemented in this algorithm. These reproductive operations form one generation of the evolutionary process, which corresponds to one iteration in the algorithm. The iteration is repeated until a given terminal criterion is satisfied.



Figure 9. Correction of ac color registration error.

RESULTS AND DISCUSSION

Some case studies have been performed to verify the effectiveness of the proposed methodology. A multiple gear system shown in Figure 8 was used for the correction of the ac component of the color registration error. In this system, the OPC drum pitch *L* is 54 mm and the diameter of a drum d_{drum} is 24 mm. Provided that the angular velocity of a motor pinion is constant, the reduction ratio from first idle gear to a coupling gear one-by-one is considered to satisfy a necessary condition for the synchronization. According to Eq. (4), the *k* values in the multiple gear system become 1.3, 0.6, 1.3, and 1.3, which are not close to integral. Owing to the inadequate reduction ratio, the runout of all gears may affect the ac component of the color registration error badly. In this study, we considered that the eight gears (upper: 4, lower: 4) marked in Fig. 8 had runout.

Assuming that the runout of the gears is sinusoidal and the peak-to-peak amplitude is 30 μ m, it is expressed from the datum mark as shown in Fig. 8. The correction of the ac color registration error to be formulated was defined as Eq. (1) and the design variables were the installation phases of eight gears with runout. CEAs for this study are set up: population size is 30; standard deviation is 0.5; mutation rate is 0.01. Also, proportional selection method is adopted for the selection process. The iteration is repeated until the generation reaches 50.

Figure 9 illustrates the result of the correction of the ac color registration error. Fig. 9(a) and 9(b) show the convergence history of the objective function and the ac color registration error in adopting the installation phases in Fig. 9(c) to the multiple gear system. The ac color registration error



Figure 10. Improved multiple gear system.

generated in this system cannot be corrected due to the inadequate reduction ratio.

To tackle the problem of the above-mentioned system, a multiple gear system shown in Figure 10 was improved based on Eq. (4) under the physical constraints. The k values in new gear system become 1.01, 1.01, 1.01, 2.01, and 2.01 to satisfy a necessary condition for the synchronization.

Figure 11 illustrates the result of the correction of the ac color registration error in the improved multiple gear system. Figs. 11(a) and 11(b) show the convergence history of



Figure 11. Correction of ac color registration error in improved multiple gear system.



Figure 12. ac color registration error in having the remaining gears with runout installed randomly.



Figure 13. Runout profiles of coupling, idle, and reduction gears.

the objective function and the ac color registration error in adopting the installation phases in Fig. 11(c). We found out that the ac color registration error could be completely removed thanks to the reduction ratio of the improved multiple gear system. Even if the remaining gears had runout under the optimal installation phases of eight gears with runout and were installed randomly, the position variation of each color was synchronized as shown in Figure 12. In both cases, their runout is sinusoidal and the peak-to-peak amplitude is 30 μ m.

The proposed methodology was actually applied to the tandem color laser printer shown in Fig. 2 and the effectiveness was verified experimentally. As the optimal installation phases in the above-mentioned case studies are obtained on the assumption that the runout profile is sinusoidal, an actual profile of the runout is required to find out the practical installation phases. The gears used in this system are injection molded plastic ones and their runout profile is measured by using a Double Flank Gear Rolling testing instrument (DF-10/MT Type, TechnoMax, Inc.). Figure 13 shows the runout profiles of three sorts of gears applied to the improved multiple gear system. They are generally different from the ideal one as shown in Fig. 6 because they depend on injection molding conditions and a gate position, etc. However, if they can be represented approximately by the Fourier series, the fluctuation of the angular velocity of the gears can be obtained by substituting the even and odd Fourier coefficients into Eq. (11).



Figure 14. Correction of ac color registration error and comparison between the simulation result and the experimental one.

Figure 14 illustrates the optimal installation phases for the correction of the ac color registration error and the comparison between the simulation result and the experimental one. The experimentally obtained result is quite similar to the simulation one and the period length of their position variation corresponds to OPC drum pitch (54 mm) owing to the proposed reduction ratio based on Eq. (3). The difference of amplitude appears, but it is caused by the remaining gears with runout as shown in Fig. 12.

CONCLUSION

The ac component of the color registration error in the paper feeding direction was corrected through the adjustment of the installation phases of gears with runout. The fluctuation of the angular velocity of OPC drums was considered as a key factor for the ac color registration error and it was mainly caused by gears with runout in the driving system. In order to express the fluctuation mathematically, the kinematical relation between a pair of gears with runout was constructed and it was extended into a multiple gear system. Also, the specific reduction ratio in the multiple gear system was proposed as a necessary condition for the correction of the ac color registration error. With the ac color registration error obtained by integrating the angular velocity of each drum, the optimization problem was formulated in terms of the installation phase of the gears with runout. CEAs were used to find the optimal installation phases.

Both simulation results and an experimental one were presented to demonstrate the feasibility and effectiveness of the proposed methodology. From the case studies, it was found that the multiple gear system should be developed based on the reduction ratio requirements for the correction of the ac color registration error. The comparison between two results showed that our approach synchronized the position variation of four colors due to the fluctuation of the angular velocity of OPC drums very well.

ACKNOWLEDGMENT

The authors would like to thank KiHwa Precision Co. Ltd. for measuring the runout profiles of the injection molded plastic gears used in this work.

REFERENCES

- ¹P. Jeran, A. J. Parker, and S. Korol, *Proc. IS&T's NIP19* (IS&T, Springfield, VA, 2003) p. 537.
- ²V. Castelli, J. deJong, and L. Williams, Proc. SPIE 2658, 96 (1996).
- ³K. Sakai, Proc. IS&T's NIP22 (IS&T, Springfield, VA, 2006) p. 568.
- ⁴K. Asakura, M. Yoshikawa, M. Aizawa, and N. Tajima, Proc. IS&T's NIP15 (IS&T, Springfield, VA, 1999) p. 604.
- ⁵M.-B. Shim, T. Furukawa, S. Yoshimura, G. Yagawa, and M.-W. Suh, Eng. Comput. **19**, 22 (2002).
- ⁶M.-B. Shim and M.-W. Suh, J. Sound Vib. 262, 141 (2003).
- ⁷A. Kahraman and R. Singh, J. Sound Vib. **142**, 49 (1990).
- ⁸A. Kahraman, ASME J. Mech. Des. 116, 706 (1994).
- ⁹H. N. Özgüven and D. R. Houser, J. Sound Vib. 121, 383 (1988).
- ¹⁰T. Kusuda, M. Ikeda, T. Ogiri, and T. Besshi, Proc. IS&T's PICS (IS&T, Springfield, VA, 1999) p. 119.
- ¹¹T. Oiwa, J. Soc. Precis. Eng. **68**, 244 (2002)(in Japanese).